

	Type	Hits	Search Text
1	BRS	520	238/10R
2	BRS	0	"railway infracture" same construction
3	BRS	10	"railroad structure"
4	BRS	204	238/2
5	BRS	165	238/3
6	BRS	134	238/4
7	BRS	125	238/5
8	BRS	143	238/6
9	BRS	212	238/7
10	BRS	229	238/9
11	BRS	1210	"road construction"
12	BRS	8	"road construction" and 238/\$.ccls.
13	BRS	19	"road construction" with air
14	BRS	0	"steel deck" same roadway
15	BRS	1	"steel deck" and 238/\$.ccls.

	<b>DBs</b>	<b>Time Stamp</b>	<b>Comments</b>	<b>Error Definition</b>
1	USPAT	2000/08/31 09:28		
2	USPAT	2000/08/31 09:29		
3	USPAT	2000/08/31 09:30		
4	USPAT	2000/08/31 09:31		
5	USPAT	2000/08/31 10:15		
6	USPAT	2000/08/31 11:17		
7	USPAT	2000/08/31 11:22		
8	USPAT	2000/08/31 11:28		
9	USPAT	2000/08/31 11:39		
10	USPAT	2000/08/31 13:47		
11	USPAT	2000/08/31 14:00		
12	USPAT	2000/08/31 14:01		
13	USPAT	2000/08/31 14:13		
14	USPAT	2000/08/31 14:14		
15	USPAT	2000/08/31 14:14		

	Type	Hits	Search Text
1	BRS	1	4415892C1
2	BRS	3	"916830"
3	BRS	338	238/8
4	BRS	231	238/9
5	BRS	104	238/25
6	BRS	60	238/128
7	BRS	34	238/129
8	BRS	44	238/149
9	BRS	199	238/122
10	BRS	134	238/264
11	BRS	218	238/336
12	BRS	147	238/382
13	BRS	293	238/2
14	BRS	463	238/283

	<b>DBs</b>	<b>Time Stamp</b>	<b>Comments</b>	<b>Error Definition</b>
1	Derwent	2000/07/27 08:31		
2	Derwent	2000/07/27 08:09		
3	USPAT; USOCR; EPO; JPO; Derwent	2000/07/27 08:31		
4	USPAT; USOCR; EPO; JPO; Derwent	2000/07/27 08:31		
5	USPAT; USOCR; EPO; JPO; Derwent	2000/07/27 08:31		
6	USPAT	2000/07/27 08:32		
7	USPAT	2000/07/27 08:33		
8	USPAT	2000/07/27 08:33		
9	USPAT	2000/07/27 08:33		
10	USPAT	2000/07/27 08:33		
11	USPAT	2000/07/27 08:34		
12	USPAT	2000/07/27 08:34		
13	USPAT; USOCR; EPO; JPO; Derwent	2000/07/27 08:35		
14	USPAT	2000/07/27 08:37		